



Report to Mayor and Council
June 21, 2021

Rounds

	May	YTD
2015	4,390	6,833
2016	3,691	6,405
2017	3,890	7,483
2018	3,649	5,188
2019	3,955	6,236
2020	1,686	3,075
2021	4,415	8,549

The main irrigation line attached to the Back 9 Bridge suffered a major crack and has been disconnected. We received a quote to have a new 8" line directionally bored under the creek in HDP and removing the risk of the line being attached to the bridge. The goal is to have that completed as soon a welding contractor and prices for supplies are received and approved.